HABS No. 252

ELLERY CORY HOUSE 24 Pioneer Street Cooperstown, Otsego Township Otsego County, New York

HARS - NY, 39-600P, 4-

PHOTOGRAPHS WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Eastern Office, Division of Design and Construction
120 South Third Street
Philadelphia 6, Pennsylvania

HISTORIC AMERICAN BUILDINGS SURVEY

ELLERY CORY HOUSE

Street Address: 24 Pioneer Street, Cooperstown, Otsego Township, (Page 1)

HABS N.Y.

39,000%

Otsego County, New York

Present Owner: Clark Estate, Main Street, Cooperstown, New York

PART I. HISTORICAL INFORMATION

A. Physical History:

- 1. Original and subsequent owners: Ellery Cory; Collins; Clark Estate
- 2. Date of erection: About 1820
- 3. Notes on alterations and additions: Kitchen built on back and porch added to the south side.

Prepared by F. Ward - October 1958

PART II. ARCHITECTURAL INFORMATION

- A. General Statement:
 - 1. Architectural character: Two-story stone house with gable roof and parapet.
 - 2. Condition of fabric: Good
- B. Technical Description of Exterior:
 - 1. Foundations: Stone
 - 2. Wall construction: Stone laid in horizontal beds
 - 3. Chimneys: Two
 - 4. Openings: a. Doorways and doors: Stone steps,
 recessed and panelled doorway, glass transom
 bar over doorway
 - b. Windows and shutters: Stone lintels and sills, with inside shutters
 - 5. Roof: Gable roof. Parapet over cornice is of solid construction.
- C. Technical Description of Interiors:
 - 1. Stairways: Enclosed
 - 2. Flooring: Wood

- 3. Wall and ceiling finish: Papered walls, plastered ceilings
- 4. Lighting: Electricity
- 5. Heating: Central and fireplaces. Fireplace in parlor has a moulded cast-iron enframement around the fireplace opening. Fireplace in dining-room was the old kitchen and has bake oven

D. Site:

- 1. General setting and orientation: Village street house on west side of street facing east.
- 2. Enclosures: Iron picket fence

Prepared by F. Ward - October 1958